



Case Study: Dairy Farm Lyle & Robyn Green, Waitaki

“What amazed me is that the lime is still in place after 8 months use. No potholes - The area is all smooth!”



Basic Facts:

- 400 hectare dairy farm
- 1450 cows
- JakMat laid in July 2010
- 280 m² covered by JakMat

Main problem areas on the farm:

Races leading into and out of the milking shed

Achievements:

- Aggregate is kept in place
- No potholes & or bogging up on main pressure areas
- No maintenance was required since JakMat installation
- High integrity of lime surface is given



JakMat laid onto a prepared base in front of the milking shed.



The same race as on the left picture covered with JakMat and filled with lime - After 8 months usage.



Race leading into the milking shed after 8 months usage. The soft metal is still in place & the integrity of the surface is preserved.



Entry to the milking shed showing a smooth & pothole free transition from race to concrete after 8 months usage.